

## **TWINNER Troubleshooting**

If you encounter a problem, try the following procedure, starting with step 1.

If step 1 did not solve the problem, go directly to step 2, etc.

1. Turn off the TWINNER  
Wait 10 s  
Turn on the TWINNER
  
2. Eject the battery  
Wait 10 s  
Insert the battery and turn on the TWINNER
  
3. Connect the charger  
Wait 10 s  
Disconnect the charger and turn on the TWINNER